

HABS
OHIO

78-KIN

1-

Congregational-Presbyterian Church

Route 5

Kinsman

Trumbull County, Ohio

Congregational & Presbyterian Church
Kinsman, Ohio

OHIO
78-101
15
HABS No. O-247

Owner (or Custodian) Church

Date of Erection Built about 1833

Architect William Smith

Builder

Present Condition In good condition. The old pews
were replaced in 1879 by the
present pews.

Number of Stories One story

Materials of Construction Frame building

Other Existing Records: Three drawings
Three photographs
One page of history

Additional Data:

**DATA NOT COMPILED AND NOT GUARANTEED
BY LIBRARY OF CONGRESS**

W

6/14/37

Congregational & Presbyterian Church
Kinsman, Ohio

PARS No. O-247

The following paper was read by Clyde B. McCurdy, Sunday August 12, 1833, at the Centennial exercises of the dedication of the present Congregational and Presbyterian Church Edifice.

In the winter of 1831-32 preparations began to be made for erecting a new and larger house of worship. The cost of the building was not far from \$4,000. One fourth of this was defrayed by Mrs. Rebecca Kinsman, who also gave the bell some years later.

The house was first occupied as a place of worship the second Sunday in August, or August 11, 1833, the First Communion in it was held the Sabbath following August 18. In the year 1879 it was repaired, the old box pews, being replaced by the present pews.

William Smith was the Master Architect, and copied from a House of Worship, called the Old North Church, in New Haven, Connecticut.

Historic American Buildings Survey
William A. Bohnard, District Officer
9815 Newton Ave., Cleveland, Ohio

**DATA NOT COMPILED AND NOT GUARANTEED
BY LIBRARY OF CONGRESS**

Addendum to
Congregational-Presbyterian Church
State Route 5
Kinsman
Trumbull County
Ohio

HABS No. OH-247

MADE
OHIO
78-KIN
1-

PHOTOGRAPHS

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, D.C. 20240